- Booster RF Cavity LCW Isolation Valve Replacement.
 - 8 valves and unions previously replaced
 - An additional 10 valves and unions were replaced during long shut-down. The remaining 20 will be replaced when possible coordinate with cavity rework schedule.
 - Remaining Stations: 9, 10, 11, 12, 13, 14, 15, 16, 17, 18
- Booster Bus LCW Strainer and Isolation Valve Replacement.
 - Remove existing Y-strainers and replace with basket strainers at wall opposite beamline. Replace isolation valves.
 - Strainers at 6 locations were installed: 1, 3, 6, 7, 13, & 19
 - Basket strainer and parts for the remaining 7 locations have been purchased and will be installed when possible.

Booster Cavity LCW Isolation Valve Replacement



Old Valves at 03 & 04



New Valves at 03 & 04

Booster Cavity LCW Strainer & Isolation Valve Replacement



Old Strainer & Valves at 07




New Strainer and Valves at 07

- Finish connection of LCW Return piping in East and West Booster Galleries to LCW Return piping at CUB.
 - All work was completed at the end of August 2012
- LCW Return Pump at CUB
 - Remove northern most old, existing return pump, and install previously purchased pump, and relocate valves to allow return pump isolation.
 - All work was completed early October 2012

LCW Return Pump and LCW Return Piping at CUB





- Install LCW Isolation Valves in CUB Utility Tunnel
 - Work is complete
- EDWA Magnets
 - Repipe EDWA magnet coils in parallel instead of in series
 - Work is complete
- Remove LCW Piping for Long 13 New Absorber
 - Remove sections of 95LCW piping and cap
 - Remove sections of 55LCW Supply and Return
 - Work is complete

LCW Enclosure Isolation Valves in CUB Utility Tunnel



New Valve in LCW Return from Enclosure



New Valve in LCW Supply to Enclosure

Remove LCW Piping for Long 13 New Absorber



Removed 55 LCW and Capped 95 LCW



Removed 55 LCW and 95 LCW

Miscellaneous LCW Work

- Magnet bus hose fittings for drainage
- Repair Choke leaks and Choke Tubing
- Remove Candy Cane Stop-Cocks and plug
- Replace Long 3 LCW Hoses
- Replace 400 MeV LCW hoses up chute
- Install LCW bypasses at return valves in the Galleries
- Work above is complete

- Booster Refill, Leak Testing, Commissioning and Balancing
 - Booster LCW has been refilled
 - Leak checking complete (never really complete!)